Summer Projects Update

July 29, 2019

Water Heater Replacement





New STEM Lab —Before Renovation





After Casework Demolition






Asbestos Removal




Enlarged Window for Student Supervision


















MMS Foyer Leak






Media Center Carpet - MMS




Life Safety – Replacement Door Locks





Life Safety – Replacement Fire Doors







Life Safety – Adding Visual Fire Alarms



Life Safety - Room 306 - Adding a Univent



Chimney Tuckpointing



Garage Renovation









Playground Replacement









